

SECRET

PRIORITY

OUT53644

P 242046Z
FM NPIC WASHDC *multi*
TO RUCSBR/SAC OFFUTT AFB OMAHA NEB
RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA
RUCVAA/2D RTS BARKSDALE AFB LA
RUEAHQ/DIA WASHDC
RUECYG/NAVRECONTECHSUPPCEN SUITLAND MD
RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF
RUWGAA/2AF BARKSDALE AFB LA
BT
S E C R E T CITE NPIC 2483

1964 JUN 24 22 02Z

25 JUN 1964

~~RRS~~
CJS
CFC
PNS
ACL

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI).

1. CAMERA B 15 WAS USED IN MISSION 3915 FLOWN ON 22 JUNE 1964; PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

Grace (File)

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: EDGE STATIC IS NOTED INTERMITTENTLY ALONG THE INBOARD EDGE OF THE FILM. A PLUS DENSITY STREAK IS APPARENT PARALLEL TO AND 3.25" FROM THE INBOARD EDGE WHEN THE DENSITY LEVEL IS FAVORABLE. MINOR PROCESSING STREAKS ARE PRESENT THROUGHOUT. A ROW OF MINUS DENSITY DOTS, SPACED 1.55" APART, IS LOCATED PARALLEL TO AND 1.95" FROM THE OUTBOARD EDGE OF THE FILM. PINHOLES ARE FOUND INTERMITTENTLY IN A ROW SPACED 3.2" APART, PARALLEL TO AND 0.25" FROM THE INBOARD EDGE THROUGH THE LAST HALF OF THE MISSION. FOGGED PATCHES ARE NOTED ON FRAMES 0001, 0003 AND 2086. A TRANSVERSE MINUS DENSITY STREAK IS PRESENT ON FRAME 0002. A WATER OR CHEMICAL STAIN CAUSING A SMALL EMULSION LIFT IS LOCATED ON FRAME 0932. A GROUP OF SMALL PLUS DENSITY COMETS IS CONTAINED IN FRAME 2302. A HEAT SPLICE OCCURS IN FRAME 1209 AND

-PAGE 2-

MANUFACTURER'S SPLICES ARE FOUND IN FRAMES 0597 AND 1884.

C. 9L SIDE: EDGE STATIC APPEARS ALONG BOTH INBOARD AND OUTBOARD EDGES OF THE FILM FROM HEAD TO TAIL OF THE MISSION. TRANSVERSE BANDS OF VARYING DENSITY ARE PRESENT CONTINUALLY FROM THE BEGINNING THROUGH FRAME 0020 AND INTERMITTENTLY THEREAFTER. A PLUS DENSITY SPOT CAUSED BY AN INTERNAL CAMERA REFLECTION IS LOCATED 2.0" FROM THE DATA CHAMBER ALONG THE INBOARD EDGE. A HEAT SPLICE WITH ASSOCIATED HANDLING MARKS APPEARS ON FRAME 1162. A MANUFACTURER'S SPLICE OCCURS ON FRAME 1413.

D. BOTH SIDES: PRESSURE ROLLER STATIC (CHATTER) IS OBSERVED ALONG BOTH EDGES OF BOTH SIDES THROUGH THE FIRST HALF OF THE MISSION. TITLED FRAMES ON BOTH SIDES ARE NUMBERED 0000-2389.

E. NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING ANOMALIES ARE NOTED ON THIS MISSION.

3. POSITIVE:

A. PRINTING AND PROCESSING WERE GOOD.

B. PI SUITABILITY IS GOOD WHERE NOT DEGRADED BY ATMOSPHERIC CONDITIONS OR VEHICLE MANEUVERS.

C. CLOUDS DEGRADE OR OBSCURE APPROXIMATELY 30 PERCENT OF THE MISSION. SCP-1

S E C R E T

-END OF MESSAGE-

(ALSO PASSED CIA WATCH (CGS))